



Pre-purchase Inspection Report

2013 MASERATI GRANTURISMO

Reference number: 1628651940

Inspection Completed On: 2021-08-12

Basic Vehicle Information

Vin - **ZAMUN45D000067974**

Registration No. - **SJW65**

Body Type - **2D COUPE**

Transmission - **6 SP AUTO SEQUENTIAL**

Exterior Colour - **BLACK**

Interior Colour - **BLACK**

Odometre Reading - **29768**

Overall Report Summary

Notes from the mechanic

*The car present is in a good condition based on age and mileage, there are few minor scratches around the car and stone chips on the front lip. No major issues seen, transmission works fine and engine doesn't make an abnormal noise. The only issue with the car is the the rear bumper and boot colours are not 100% matching.
Car inspector- omid*

Omid Bonab - Inspector

Our Scoring Scale

Excellent - Brand new/ recently replaced/ no evidence of fault detected

Good - Item found to be in working order with some signs of damage and/or deterioration, consistent with the age & kilometers of vehicle

Fair - Item found to be in working order with notable signs of damage and/or deterioration, consistent with the age & kilometers of vehicle

Poor - Item found to be in bad condition, needs urgent attention or replacement

N/A - Item not fitted to the vehicle or able to be checked

Attention Required

Build plate

Rating: Poor

Comments: Not found



Compliance plate

Rating: Poor



Car Photos





Full Report

Engine:

Engine bay presentation

Rating: Good



Running noise

Rating: Good

Oil level

Rating: Good

Coolant level

Rating: Good

Washer fluid level

Rating: Good

Brake fluid level

Rating: Good

Fluid leaks

Evident: No

Mountings

Rating: Good

Hoses & Pipes

Rating: Good

Water pump / Fan

Rating: Good

Ignition System / Distributor

Rating: Good

Fuel System

Rating: Good

Battery Voltage

Rating: Fair

Battery terminal condition

Rating: Fair

Radiator & Cap

Rating: Good

Drive belt & pulleys

Rating: Fair

Brake Booster


Rating: Fair

Master Cylinder / ABS

Rating: Fair

Faults detected during diagnostic scan

Evident: No



Interior:

Owners manual/keys

Evident: Yes



Dash board condition

Rating: Fair

Comments: Minor scratches around dashboard



Seats

Rating: Good

Seat belts

Rating: Good

Floor mat condition

Rating: Good

Boot condition

Rating: Good

Trims

Rating: Good

Radio

Rating: Good

Speaker operation

Rating: Good

Rear window demister

Rating: Not Applicable

Air Conditioning

Rating: Good

Heater demister

Rating: Good

Washers & Wipers

Rating: Good

Horn working

Evident: Yes

Doors, locks, & hinges

Rating: Good

Window operation

Rating: Good

Warning lights

Evident: No

All interior lights working

Evident: Yes

Gear lever condition

Rating: Good

Exterior:

Rust

Evident: No

Windscreen

Rating: Good

Windscreen Wiper Rubbers

Rating: Good

Evidence of Damage

Evident: Minor

Comments: A slight colour difference between rear panel and boot



Glass/ Mirrors

Rating: Good

Sunroof / Convertible operation

Rating: Not Applicable

Visible frames & members

Rating: Good

Front Suspension

Rating: Good

Rear Suspension

Rating: Good

Steering Components

Rating: Good

Exhaust

Rating: Good

Differential

Rating: Good

Drive Shafts

Rating: Good

Underbody

Rating: Fair

All exterior lights working

Evident: Yes

Compliance plate


Rating: Poor



Build plate

Rating: Poor

Comments: Not found it



General condition aside from cleanliness

Rating: Good

Wheels:

Spare tyre/rim/tool kit

Evident: Not Applicable

Brake hoses / callipers

Rating: Good

Front brakes

Rating: Fair

Rear brakes

Rating: Fair

Park brake

Rating: Good

LHF tyre condition

Rating: Fair



LHR rim condition

Rating: Good



LHR tyre condition

Rating: Fair



RHR rim condition

Rating: Good



RHR tyre condition

Rating: Fair



RHF rim condition

Rating: Good



RHF tyre condition

Rating: Fair



LHF rim condition

Rating: Good



RoadTest:

Ease of starting

Rating: Good

Engine noise

Rating: Good

Engine performance

Rating: Good

Exhaust smoke / Emissions

Rating: Good

Gearbox operation

Rating: Good

Brake shudder

Evident: No

Clutch shudder

Evident: Not Applicable

Differential noise

Evident: Not Applicable

Steering / Suspension

Rating: Good

Brake operation

Rating: Good

Instrument cluster operation

Rating: Good

Cruise Control

Rating: Good

4WD System

Rating: Not Applicable

Engine operating temperature

Rating: Good

Wheel bearings

Rating: Good

Report Disclaimer

1. Car Inspect Pre Purchase inspections are visual condition reports only which are performed by hand-picked, accredited mobile mechanics. The report provided by the mobile mechanics is intended to summarise the overall condition of the vehicle based on the checklist items set out in the report. This report does not act as a roadworthy certificate or safety certificate in any way for any Australian state or territory.
2. Although every intention will be made to accurately summarise the vehicle's condition in the environment that the seller proposes for the inspection to take place, the condition of some checklist items may be deemed too difficult for the mobile mechanic to draw an accurate conclusion on based on external factors such as weather, cleanliness of vehicle or location, this will be specified in the report by the mobile mechanic.
3. The report conducted by the accredited mobile mechanic only takes into consideration the condition of the stated checklist items at the specified date and time of the inspection. Under no circumstance will the trading company Car Inspect Pty Ltd or its parent company Team Inspect Pty Ltd be responsible for any defects with the vehicle that arise during or after the inspection takes place.
4. The inspection specifically covers the vehicle's exterior, interior, engine compartment, tyres and wheels, brakes, underbody and a road test where possible. No removal of parts or components is undertaken during the inspection process. You acknowledge that while the mobile mechanic uses accepted methods for fault detection, these methods will not necessarily identify all faults with a vehicle. You should consider the age, mileage and condition of the vehicle at the time of inspection and the report should be reviewed in this context. Vehicles are only road tested to the speed limit of the local area which may affect the mobile mechanic's ability to draw an accurate conclusion on some checklist items.
5. Apart from noting the tread wear of the tyres, the mobile mechanics do not check the correct tyre sizes are fitted, the age, the load rating or that the manufacturer's specified and approved oils, fluids and coolants are fitted to the vehicle.
6. Items checked during the inspection are those stated in the checklist items only, the mobile mechanic WILL NOT check the condition of fuel and oil consumption, timing belts or chain, alarm/ security systems, trip meters / computers, Head units, navigation / GPS, TV, cassette or disc player, auto wipers and adaptable lights. The mobile mechanic will also not check for water leaks or moisture ingress. The mobile mechanic does not check any filters including diesel particulate filters and catalytic converters. Please refer to manufacturer's specifications for replacement of timing belts, and filters in service records. The mobile mechanic does not inspect the engine internals, which include fuel injectors, EGR valves nor how much sludge or carbon build up which are normally found in diesel engines.
7. The report provided by the mobile mechanic to you is only current as at the time it is issued. It is the buyer's responsibility to conduct their own visual inspection of the vehicle at the point of sale as the mobile mechanic can only advise on the condition of the vehicle at the time of inspection. You acknowledge that the mobile mechanic does not check for any manufacturer recall notices and all buyers should check that the vehicle is not subject to any recall notices.
8. You accept that Car Inspect nor the accredited mobile mechanic who performed the inspection will play no role in the sale terms of the vehicle.
9. All third party Accredited mobile mechanics hold their own insurances and are fully qualified for vehicle pre-purchase inspection work.
10. Although Carinspect is confident in the accuracy of the data generated through the CarHistory platform, Carinspect bears no responsibility for the accuracy of the 3rd party data generated.