

3RD PARTY INDEPENDENT VEHICLE INSPECTION REPORT

DISCLAIMER

1. This 3rd Party Independent Vehicle Inspection Report (Report) is a summary of the findings of the 3rd Party Independent Vehicle Inspector (Inspector) only and in no way reflects the opinions or views of CHROME TEMPLE Motors.
2. CHROME TEMPLE Motors cannot accept any liability for the information provided in this Report.
3. The Report provided by the Inspector is only current as at the time it is issued.
4. You agree that as the buyer or interested party, it is your ultimate responsibility to conduct your own due diligence as far as to satisfy your own requirements on the vehicle.
5. The inspection is a visual inspection only. There will be no removal of parts or components during the inspection process, unless otherwise stated by the Inspector.
6. You accept that while the Inspector may use a range of methods for fault detection, they will not necessarily identify all faults with the vehicle.
7. The Report is not a roadworthy certificate and cannot be used as a roadworthy.
8. The Inspection does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.
9. CHROME TEMPLE Motors does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you.
10. CHROME TEMPLE Motors will not be liable to you for claims arising out of or in connection with your access and use of this Report.

INSPECTING COMPANY:	Auto Excel
INSPECTOR NAME:	Kriss Ivison
DATE OF INSPECTION:	20/11/21
MAKE & MODEL:	Toyota Supra
MODEL YEAR:	1994
BUILD DATE:	1994
COMPLIANCE DATE:	1994 (1989)
VIN / CHASSIS NUMBER:	JZA80-0005500
REGISTRATION EXPIRY:	16/09/22
REGISTRATION NUMBER:	210C77
ODOMETER READING:	163472

REPORT INSTRUCTIONS:

Please check all relevant points within this report and note your findings with a score and description, where attention is required. Once complete, add a post-report summary of the vehicle. Scoring to be used:

GREAT: Excellent condition

GOOD: Above average condition

FAIR: Average or expected condition for KM and/or age

ATTENTION: In need of attention or repair. Add a description of your findings

NA: Not applicable

0.00 POST-REPORT VEHICLE SUMMARY

This vehicle is in overall excellent condition inside and out with some defects to report, however none of these defects are classed as serious or dangerous.

The car has had a full body restoration and modifications done to an extremely high standard with quality aftermarket parts installed.

The Supra is at a very high state of tune which is notable to how it drives and sounds.

1.00 EXTERIOR CONDITION		SCORE & DESCRIPTION
1.01	Paintwork	Great
1.02	Bodywork	Great
1.03	Rust	Great
1.04	Damage	Great
1.05	Convertible roof / soft-top	Great
1.06	Trim & finishers	Great
1.07	Glass	Great
1.08	Mirrors	Great
1.09	Lamps	Great
1.10	Engine bay panels and soundproofing	Great
1.11	Under body frame, panels & mouldings	Great
1.12	Other exterior checks	
2.00 INTERIOR CONDITION		SCORE & DESCRIPTION
2.01	Metal & composite surfaces	Good
2.02	Leather & upholstery	Great
2.03	Headlining	Great
2.04	Steering wheel	Great
2.05	Carpets & mats	Great
2.06	Seats	Great
2.07	Seat belts, buckles & catches	Great
2.08	Switches	Great
2.09	Controls	Great
2.10	Gauges	Great
2.11	Other interior checks	

This report is a summary of the findings of the 3rd Party Inspection Company only and in no way reflects the opinions or views of CHROME TEMPLE Motors.

3.00	GENERAL FUNCTION	SCORE & DESCRIPTION
3.01	Locks, catches & handles	Great
3.02	Keys	Great
3.03	Security system	Attention: Central locking not working; only one key available
3.04	Windows	Great
3.05	Interior mirrors	Great
3.06	Seats	Great
3.07	Seat belts	Great
3.08	Bonnet, boot & fuel cap release	Great
3.09	Steering column adjustment	Great
3.10	Foot brake, parking brake & handbrake	Great
3.11	Gauges & warning lights	Great
3.12	Switches & controls	Great
3.13	Infotainment, stereo, speakers & GPS system	Great
3.14	Storage compartments	Great
3.15	Wipers & washers	ATTENTION: Inoperation Front + Rear washer
3.16	Heated screens	Great
3.17	Exterior lights, lamps & indicators	Great
3.18	Interior lights	Great
3.19	Instrument illumination	Great
3.20	Horn	Great
3.21	Heating, air-conditioning & ventilation	ATTENTION: A/C low efficiency
3.22	Convertible roof	Great
3.23	USB & cigarette lighter sockets	Great
3.24	Tyre pressure monitor	N/A
3.25	Other function checks	

4.00 HISTORY, PLATES, KEYS & TOOLKIT		SCORE & DESCRIPTION
4.01	Log book	ATTENTION: None
4.02	Service history	ATTENTION: None
4.03	Build & compliance plates	Great
4.05	2 keys	ATTENTION: 1 Key
4.06	Toolkit & emergency equipment	ATTENTION: None
4.07	Other service history & toolkit checks	ATTENTION: None
5.00 WHEELS & TYRES		SCORE & DESCRIPTION
5.01	Wheels condition	Great
5.02	Wheel bearings	Great
5.03	Front wheel alignment	Great
5.04	Spare wheel	ATTENTION: None
5.05	Tyre spec	ATTENTION: Non-standard compliance, tyres front and rear; rear tyres have low tread depth
5.06	Tyre pressures	Great
5.07	Tyre depths & condition	ATTENTION: x2 Rear tread depth low
5.08	Other wheels & tyres checks	
6.00 ENGINE BAY, UNDERBODY, FLUID LEVELS & LEAKS		SCORE & DESCRIPTION
6.01	Engine	Great
6.02	Transmission	Great
6.03	Differential	Great
6.07	Oil	Great
6.08	Coolant	Great
6.09	Brake fluid	Great
6.10	Clutch fluid	Great
6.11	Battery	Great
6.04	Ignition system	Great
6.06	Power steering system	Great
6.12	Fuel system	Great
6.13	Air-conditioning system	ATTENTION: Low efficiency
6.15	Radiators, oil coolers, intercoolers, hoses & pipes	Great

6.16	Water pump & fan	Great
6.05	Drive shafts	Great
6.14	Drive belts & pulleys	Great
6.17	Gaiters	Great
6.18	Dampers	Great
6.19	Exhaust system	Great
6.20	Brake pads & discs	Great
6.21	Brake hoses & pipes	Great
6.22	Steering & suspension components	Great
6.23	Fluid leaks	ATTENTION: Minor engine oil leak in an undetermined area.
6.25	Underbody	Great
6.26	Other engine, underbody, levels & leaks checks	Great
7.00	ROAD TEST	SCORE & DESCRIPTION
7.01	Engine start, idle & performance	Great
7.02	Exhaust smoke	Great
7.03	Clutch	Great
7.04	Transmission	Great
7.05	Differential	Great
7.06	Brakes	Great
7.07	ABS & traction control	Great
7.08	Suspension & dampers	Great
7.09	Steering & steering wheel alignment	Great
7.10	Cruise control	Great
7.11	Noise & vibration	Great
7.12	Instruments, gauges, temperatures & pressures	Great
7.13	Other road test checks	Great
8.00	POST ROAD TEST	SCORE & DESCRIPTION
8.01	Dash lights & fault codes	Great
8.02	Leak check (post road test)	Great
8.03	Other post road test checks	Great

This report is a summary of the findings of the 3rd Party Inspection Company only and in no way reflects the opinions or views of CHROME TEMPLE Motors.