

3RD PARTY INDEPENDENT VEHICLE INSPECTION REPORT

DISCLAIMER

1. This 3rd Party Independent Vehicle Inspection Report (Report) is a summary of the findings of the 3rd Party Independent Vehicle Inspector (Inspector) only and in no way reflects the opinions or views of CHROME TEMPLE Motors.
2. CHROME TEMPLE Motors cannot accept any liability for the information provided in this Report.
3. The Report provided by the Inspector is only current as at the time it is issued.
4. You agree that as the buyer or interested party, it is your ultimate responsibility to conduct your own due diligence as far as to satisfy your own requirements on the vehicle.
5. The inspection is a visual inspection only. There will be no removal of parts or components during the inspection process, unless otherwise stated by the Inspector.
6. You accept that while the Inspector may use a range of methods for fault detection, they will not necessarily identify all faults with the vehicle.
7. The Report is not a roadworthy certificate and cannot be used as a roadworthy.
8. The Inspection does not check for any manufacturer recall notices and you should check that the vehicle is not subject to a recall notice.
9. CHROME TEMPLE Motors does not provide any guarantee, warranty or representation regarding the nature, reliability, accuracy or completeness of any information contained in the Report or the fitness of the information contained in the Report for any purpose intended by you.
10. CHROME TEMPLE Motors will not be liable to you for claims arising out of or in connection with your access and use of this Report.

INSPECTING COMPANY:	Cavallino Motorsport pty ltd
INSPECTOR NAME:	Alessio
DATE OF INSPECTION:	
MAKE & MODEL:	Ferrari 328 GTS
MODEL YEAR:	1987
BUILD DATE:	
COMPLIANCE DATE:	10/87
VIN / CHASSIS NUMBER:	ZFFXA20D000072065
REGISTRATION EXPIRY:	September 2022
REGISTRATION NUMBER:	GTB328
ODOMETER READING:	57617

INSTRUCTION FOR THE REPORT:

Please check all relevant points within the report check-list. Once checked, please note your findings against each section. Once the report has been completed, please give a post-report summary of the vehicle.

0.00 POST-REPORT VEHICLE SUMMARY

The car exterior presents well, there are minor blemishes & stone chips in the paint work. All wheels & tyres are in good condition. There are no signs of major accident damage or rust. The car has been painted in the past. All under floor pieces are present & undamaged
The Interior is in good condition showing relevant patina for the age of the car. All gauges and switch gear are operational.

Engine compression is OK. Cooling system is operating as it should. thermostat function is good and cooling fans are operating when correct temps are reached.

No oil leaks present. AC is inop. No excessive play found on all ball joints, suspension bushes, wheel bearings and steering components. The battery is charged and good.

All books and tools are present along with good service history.

1.00	EXTERIOR CONDITION	NOTES
1.01	Paintwork	GOOD
1.02	Bodywork	GOOD
1.03	Rust	N/A
1.04	Damage	N/A
1.05	Convertible roof / soft-top	GOOD
1.06	Trim & finishers	GOOD
1.07	Glass	GOOD
1.08	Mirrors	GOOD
1.09	Lamps	GOOD
1.10	Engine bay panels and soundproofing	FAIR

1.11	Under body frame, panels & mouldings	FAIR
1.12	Other exterior checks	
2.00	INTERIOR CONDITION	NOTES
2.01	Metal & composite surfaces	GREAT
2.02	Leather & upholstery	FAIR
2.03	Headlining	FAIR
2.04	Steering wheel	FAIR
2.05	Carpets & mats	FAIR
2.06	Seats	FAIR
2.07	Seat belts, buckles & catches	GOOD
2.08	Switches	GOOD
2.09	Controls	GOOD
2.10	Gauges	GOOD
2.11	Other interior checks	
3.00	GENERAL FUNCTION	NOTES
3.01	Locks, catches & handles	GOOD
3.02	Keys	GOOD
3.03	Security system	N/A
3.04	Windows	GOOD
3.05	Interior mirrors	GOOD
3.06	Seats	GOOD
3.07	Seat belts	GOOD
3.08	Bonnet, boot & fuel cap release	GOOD
3.09	Steering column adjustment	N/A
3.10	Foot brake, parking brake & handbrake	GOOD
3.11	Gauges & warning lights	GOOD
3.12	Switches & controls	GOOD
3.13	Infotainment, stereo, speakers & GPS system	FAIR
3.14	Storage compartments	VERY GOOD
3.15	Wipers & washers	GOOD
3.16	Heated screens	N/A
3.17	Exterior lights, lamps & indicators	GOOD

This report is a summary of the findings of the 3rd Party Inspection Company only and in no way reflects the opinions or views of CHROME TEMPLE Motors.

3.18	Interior lights	GOOD
3.19	Instrument illumination	FAIR
3.20	Horn	GOOD
3.21	Heating, air-conditioning & ventilation	FAIR
3.22	Convertible roof	GOOD
3.23	USB & cigarette lighter sockets	N/A
3.24	Tyre pressure monitor	N/A
3.25	Other function checks	
4.00	HISTORY, PLATES, KEYS & TOOLKIT	NOTES
4.01	Log book	PRESENT
4.02	Service history	PRESENT
4.03	Build & compliance plates	OK
4.05	2 keys	1 KEY SET
4.06	Toolkit & emergency equipment	PRESENT
4.07	Other service history & toolkit checks	
5.00	WHEELS & TYRES	NOTES
5.01	Wheels condition	GOOD
5.02	Wheel bearings	GOOD
5.03	Front wheel alignment	GOOD
5.04	Spare wheel	PRESENT/OK
5.05	Tyre spec	225/50/16 205/55/16
5.06	Tyre pressures	GOOD
5.07	Tyre depths & condition	GOOD
5.08	Other wheels & tyres checks	
6.00	ENGINE BAY, UNDERBODY, FLUID LEVELS & LEAKS	NOTES
6.01	Engine	GOOD
6.02	Transmission	GOOD
6.03	Differential	GOOD
6.04	Oil	NEW
6.05	Coolant	GOOD

This report is a summary of the findings of the 3rd Party Inspection Company only and in no way reflects the opinions or views of CHROME TEMPLE Motors.

6.06	Brake fluid	REQUIRES REPLACEMENT
6.07	Clutch fluid	GOOD
6.08	Battery	GOOD
6.09	Ignition system	GOOD
6.10	Power steering system	GOOD
6.11	Fuel system	N/A
6.12	Air-conditioning system	GOOD
6.13	Radiators, oil coolers, intercoolers, hoses & pipes	INOP
6.14	Water pump & fan	GOOD
6.15	Drive shafts	GOOD
6.16	Drive belts & pulleys	GOOD
6.17	Gaiters	GOOD
6.18	Dampers	GOOD
6.19	Exhaust system	GOOD
6.20	Brake pads & discs	FAIR
6.21	Brake hoses & pipes	GOOD
6.22	Steering & suspension components	GOOD
6.23	Fluid leaks	GOOD
6.25	Underbody	N/A
6.26	Other engine, underbody, levels & leaks checks	GOOD
7.00	ROAD TEST	NOTES
7.01	Engine start, idle & performance	GOOD
7.02	Exhaust smoke	GOOD
7.03	Clutch	GOOD
7.04	Transmission	GOOD
7.05	Differential	GOOD
7.06	Brakes	GOOD
7.07	ABS & traction control	N/A
7.08	Suspension & dampers	GOOD
7.09	Steering & steering wheel alignment	GOOD
7.10	Cruise control	N/A
7.11	Noise & vibration	NOT PRESENT

This report is a summary of the findings of the 3rd Party Inspection Company only and in no way reflects the opinions or views of CHROME TEMPLE Motors.

7.12	Instruments, gauges, temperatures & pressures	OPERATIONAL
7.13	Other road test checks	
8.00	POST ROAD TEST	NOTES
8.01	Dash lights & fault codes	N/A
8.02	Leak check (post road test)	N/A
8.03	Other post road test checks	